

ATTACHMENT A

Photos



Photo 1: Path from Parking Lot before Construction



Photo 2: Before Construction



Photo 3: Path from Parking Lot after Construction



Photo 4: Natural Walking Path after Construction



Photo 5: Canoe Launch before Construction



Photo 6: Canoe Launch after Construction



Photo 7: Boardwalk and New Plantings



Photo 8: Observation Deck on Boardwalk




Photo 9: Helical Piers



Photo 10: New Trees and Bushes



Photo 11: New Trees and Bushes



Photo 12: Installation of Weir at Inlet Side



Photo 13: Inlet of Weir on Wetland Side



Photo 14: Outlet of Weir on River Side



Photo 15: Parking Lot before Construction



Photo 16: Parking Lot after Construction



Photo 17: New Entrance Apron, Stormwater Catch Basin and Additional Space for Parking



Photo 18: New Signs and Railing to Prevent Vehicle Traffic in Park

(Stone sculpture provided by ATPC)



Photo 19: Sign at Park Entrance



Photo 20: Sign explaining historical significance of Ashtabula Train & Bridge Disaster which occurred at bridge located at end of Natural Walking Trail.